



CWS Cleanrooms Management Service

**The best
performance now
available on-site.**

**We take care of the cleanroom area on your premises:
from logistics to equipping the airlock – so that everything
in your production works in perfect harmony.**

CWS Cleanrooms Management Service

Benefit from our experience – directly at your site.

As your partner with many years experience in cleanroom clothing, cleaning, consumables and training, we now bring our expertise directly to your company's door. We reduce your workload, help you to optimise processes and thus ensure the quality and continuity of care. With CWS personnel trained within our own Cleanroom Academy, we guarantee the highest level of safety and reliability – for the smooth running of your production environment.

Our service modules

Availability	Quality management	Logistics	Optimisation
Supply of the changing areas with cleanroom clothing	Monitoring of best-before dates for sterile clothing	Removal of dirty laundry	Process analysis and standardisation
Size-assorted filling of clothing racks	Dealing with defects and arranging for cleaning or repair	Delivery and dispatch via your goods receiving department	Improvement in your internal logistics
Replenishment of consumables	Replenishing stock levels in case of shortage	Provision of containers for dropping in the dirty laundry	Bespoke services: How can we help you?

Your benefits

- ✓ **Quality & continuity**
As an experienced and reliable partner, we guarantee the best service and highest quality on a permanent basis.
- ✓ **Relief and time saving**
Freedom to focus on your core activities and reduce your team's workload.
- ✓ **Safety**
Our employees are experienced in cleanrooms and are also specifically trained and educated for the application.
- ✓ **Cost saving and process optimization**
We help to deliver a highly efficient process and to optimise deliveries and warehousing.

Are you interested in on-site services?

We will be happy to advise you: +32 3 355 49 03 | cleanrooms.be@cws.com